Video Systems
SH, China

Honeywell SMART VIEWER Mac

Release Notes

This document contains proprietary information of Honeywell International Inc. Information contained herein is to be used solely for the purpose submitted, and no part of this document or its contents shall be reproduced, published or disclosed to a third party without the express permission of Honeywell International Inc.

Modification History

No.	*Release note Date <mm/dd/yy>*	*Changes made*	*Author*	*Reviewers*
1	*08/31/2023*	*Bug fix and support S35 NVR Pro*	*Alice*	
2	*08/20/2025*	*P2P certificate update, CS improvement, bug fix and support new alarms from NVR.*	*Alice*	

Contents

Firmware Release Document 4
Release Notes....4
Firmware Version Information (File name)....4
What's New Feature and Fixed Issue List....**Error! Bookmark not defined.**
Un-implemented Features or Functions....5
Test Report....5

Firmware Release Document

Release Notes

Product Name:	*HSV*
Product Model:	*MacOS Monterey 12.4、macOS Ventura 13.0*
Version Number:	*V1.0.68_20250820*
Release Date:	*2025/08/20*

Firmware Version Information (File name)

	Version	File name		Check Sum (SHA256)
Firmware Version	*V1.0.68_20250820*	File name	HSV_MAC_V1.0.68_20250820	7fa51141f3f573f4a0825efe7d90680b2ca89a48c948d426877046f4be8ccacb

Cyber security updates

This version supersedes all previous versions of HSV. Those olde versions will no longer receive cyber update. To Keep up to date with the latest cyber updates, please install this version as soon as practical.

What's Realized and Fixed Issue List

Build date: 2025-08-20

No.	Modification information	Type
1	Cyber security improvement	Bug fixed
2	Update HSV installation interface privacy agreement PDF document.	Improvement
3	Updated HSV License Agreement PDF document.	Improvement
4	Solve the problem of failure to add device through P2P due to certificates expired.	Bug fixed
5	Solve the problem of unconventional video encoding parameters and video decoding failure in the real-time alarm playback window	Bug fixed
6	After changing the default bitstream parameters in the system configuration to "auxiliary bitstream," the alarm event playback window page still downloads the main bitstream.	Bug fixed
7	Add device password input length consistent with the NVR, limited to 20 characters	Bug fixed
8	Solve the problem that most of the windows don't show the window overview image in playback-grid mode	Bug fixed

9	Optimize the timeout mechanism and reconnection times of P2P adding devices under weak network conditions.	Bug fixed
10	Solve the problem that users without download privileges backup and download videos, prompting that they do not have privileges, and the blue selected rendering of the timeline does not disappear.	Bug fixed
11	Solve the problem of inconsistency between real-time event alarm time and event retrieval alarm time	Bug fixed
12	Added NAS offline alarm	New feature
13	Added Auto back failed alarm	New feature
14	Added Illegal access alarm	New feature
15	Added Primary NVR reconnect alarm and logging	New feature
16	Added Redundant NVR enabled alarm and logging	New feature

Un-implemented Features or Functions

Build date:

No.	Un-implemented Features or Functions	Type

Test Report

The test report was included in the test summary.